
Installation Instruction



UNPACKING INSTRUCTIONS

- ! Carefully open the carton, remove contents and lay out on cardboard or other protective surface to avoid damage.
- ! Check package contents against the Supplied Parts List in the next page to assure that all components were received undamaged. Do not use damaged or defective parts.
- ! Carefully read all instructions before attempting installation.

IMPORTANT SAFETY INFORMATION

- ! Install and operate this device with care. Please read this instruction before installation, and carefully follow all instructions contained herein. Use proper safety equipment during installation.
- ! Please call a qualified installation contractor for help if you don't understand these directions or have any doubts about the safety of the installation.

Do not use this product for any purpose or in any configuration not explicitly specified in this instruction. We hereby disclaims any and all liability for injury or damage arising from incorrect assembly, incorrect mounting, or incorrect use of this product.

Supplied Parts List



(1) 48mm Pole-a



(1) Disconnected "C" Clamp-b



(2) Side Vesa Plate with Slip Set-c1



(1) Middle Vesa Plate-c2



(2) Long Arm-d



(1) Arm Connect Part-e



(1) Arm Clamp-f



(4)M6x25 Bolt-g



(4)M6 Washer-h



(2)Arm Plastic Cover-i



(1) Allen Key-i



(24)M4 Washer-k



(12)M4x12 Thumb Bolt-I



(12)M4x30 Bolt-m



(12)M4 Space-n



(2)M8x10 Bolt-o



(2)Wire Clip-p



(2)M4x16 Bolt with washer-q




(2)M10x15 Bolt-r




CAUTION!


This monitor desktop mount must be securely attached to the horizontal desk. If the mount is not properly installed it may fall, resulting in possible injury and/or damage.



Step 2 Assemble the Arm Sets and Install it on the Pole




Assemble the curved arm sets as the diagram above, fasten the M6x25 Bolt(g) by provided Allen Key(j).




Insert the curved arm sets to pole, fasten the M8x10 Bolt(o) by provided Allen Key(j). Install the Wire Clip(p).

Step 3 Mount the Monitor to VESA Plate








For Curved Back Monitor


Step 4

Attach the Monitors to Arm Sets




Attaching the monitors to the curved arm sets, fasten the M4x16 Bolt with Washer(q), fixing the position by the plastic knob. Install the Arm Plastic Cover(i) as the above diagram.

Adjust the Tilting Angle and the Monitors Level



Fasten the grub screw to fix the tilting angle by provided Allen Key(j).



By fasten or loosen the bolt on the above diagram to adjust the level of each monitor.

Step 6 Manage the Wires

